

### Explanation on tower work

The KABE-CD tower has failed structural and must be replaced with a new tower. A verbal agreement with the landlord has been reached for building a new tower adjacent to the existing tower and removing the original tower. Engineering and construction drawings have been completed and required zoning and permitting applications have been completed. KABE-CD will commence tower construction upon issuance of the required permits.