



March 7, 2021

**K18DL-D Logan, UT - Facility ID: 36605
Interference Check at 3.2 kW using the
SCA-PR-450CU (ID 23500) Antenna
As described in BLDTT-20080909ACR**

Attached is a TVStudy (v 2.2.5) Interference Check that shows no interference is caused by K218DL-D operating with 3.2 kW using the directional antenna that was authorized in FCC File No. BLDTT-20080909ACR). The check was run using a Simple Mask and typical 1.0 X 1.0 km study grid spacing. The proposed operation will not cause prohibited interference.


Carl E. Gluck, CPBE



Carl T. Jones Corporation
7901 Yarnwood Court, Springfield, Virginia 22153-2899 (703) 569-7704 Fax: (703) 569-6417