

WSCG, Baxley, GA (Fac. Id. 69446)
Engineering STA Extension Explanation

The WSCG transmitter suffered an equipment failure that limited transmitter output and caused the station to operate at 20-25% of its licensed power. A new transmitter has been ordered but due to scheduling and electrical issues, installation is only partially complete. At this time, installation work and resumption of full power station operations is slated for the day prior to the STA expiration. However, in an abundance of caution and to provide for any unforeseen contingencies, WSCG requests an extension of the existing engineering STA for an additional 180 days so that it is authorized to continue providing some service to the public if the STA expires without the final installation work being completed.