

FCC Form2100 Schedule 381 Exhibit

Antenna Support Structure

Question: “In what year was the last structural analysis conducted on the structure?”

Answer: We contacted the tower and tower site owner, THE KUEWA PROJECT, INC., who stated that they have never conducted such a study as they and their consultants did not believe that one was necessary or required. They are unaware of any study the previous owner may or may not have conducted. They acknowledge that the tower is overloaded but at this time they have no plans to conduct any such analysis.

Question: “Under what structural standard was the last structural analysis conducted?”

Answer: See answer above.