

## EXHIBIT 1

### ANTENNA SUPPORT STRUCTURE – STRUCTURAL ANALYSIS

The antenna support structure was built in 1980, per applicable engineering codes for Puerto Rico. The tower has been periodically maintained, as required, but no structural analysis has been performed after construction.