

Barry L. Wert, P.E., P.L.S.  
Jeffrey A. Wert, P.E., P.L.S.  
Robin K. Youmans, P.E.  
Kenneth M. Fretz, Sr., P.L.S.  
Cynthia H. VanHise, P.E.  
James R. Rudolph, P.E., P.L.S.  
Mark R. Flaherty, Survey Manager  
Joseph J. Fielder, Inspection Manager  
Wendy L. Clair, SPHR, Business Manager  
Ralph A. Wert, P.E., P.L.S. 1956-1994

Civil Engineers & Land Surveyors · 410 Derstine Avenue, PO Box 647, Lansdale, PA 19446-0608 · 215-855-3111 · Fax 855-5143


### CERTIFICATION

This is a certification that Metz Engineers performed a field survey on March, 19, and April, 24, 2007 in York County, PA. The survey was performed for Four Rivers Community Broadcasting Corporation station WZXM Middletown Pennsylvania.

The survey consisted of a solar observation to determine true north. Upon completion of our base line azimuth determination (field notes enclosed), we aligned a Shively Model 6513-2-H/V (Slant)-DA antenna system also known as the WZXM FM Antenna. The orientation of a single antenna is 101° degrees from true north.

Several field and office checks were performed to verify instrument position and azimuth direction. All checks that were made verified the fieldwork was correct. Therefore, Metz Engineers certifies that the WZXM antenna's aligned April 24, 2007 is in alignment, as specified by the manufacturer.



  
Jeffrey A. Wert, P.E., P.L.S.

5/29/07

Date