

October 30, 2014

WWEI (Originally WBEC) Replacement 6810-2D-SS-DA half wave spaced antenna

To whom it may concern;

On or about October 9th a weather related microburst caused the collapse of the support structure that WWEI's 6810-2D-SS-DA half wave spaced antenna was attached, damaging the antenna beyond repair.

The replacement antenna was constructed and tested using a new 6810-2D-SS-DA half wave spaced antenna with new parasitic elements. Providing WWEI with a precision replacement antenna. Therefore the original Proof of Performance Report is still valid.

Robert A. Surette



Director of Sales Engineering

Cc; 32147