

## Exhibit 1.

### Station – KPWC-LP Application for STA

The transmitter for KPWC-LP has been temporarily moved to another facility while that stations transmitter is sent back to the manufacturer for warrantee repair. Since this other facility serves a much larger population this will best serve the most viewers. The timeline for this repair is not yet determined. We request that this STA for up to six months be granted to allow KPWC-LP to remain silent while this repair is competed.