


FIGURE 5 - DUOPOLY EVALUATION

KMJK(FM) - 297C1 Downgrade
Lexington, Missouri



Mullaney Engineering, Inc. July 2003

70 dBu City Grade Contours

Scale 1:1,000,000

0 10 20 30 km