

Certification re: KQCI, Freer Texas

I certify that a fence has been installed surrounding the KQCI tower, 25ft. from the base of the tower the KQCI antenna is attached to. The fence is constructed in such a way to preclude casual or inadvertent access to the tower and that warning signs have been installed at approximately 10ft intervals along the fence. These signs describe the RF hazard.

KQCI station policy is that before any personnel can enter the tower enclosure, power will be reduced to 500 watts or less. Power will be turned off if personnel are required to climb the tower.

Signed

A handwritten signature in black ink, appearing to read 'Francisco Diaz', with a stylized flourish at the end.

Francisco Diaz

Manager,

CENTRO CRISTIANO COSECHA FINA